

Essential when the generator cannot be placed directly next to the welder, remote controls improve work efficiency and reduce welder fatigue.



	RC-FA1	RC-HA1	RC-HA2	RC-HD2
Length	4 m	8 m	10 m	option (2.8, 6 or 11 m)
Part number	045682	045675	047679	062122
PROGYS 220E FV CEL	✓	✓		
PROGYS FLEX 280 CEL	✓	✓		
GYSARC 300 TRI	✓	✓		
GYSARC 400 TRI	✓	✓		
EXAGON 400 CC/CV	✓	✓		
PROTIG 201 DC FV	✓	✓		
TIG 220 DC HF	✓	✓		
TIG 300 DC HF	✓	✓		
TITAN 400 DC HF	✓	✓		✓
PROTIG 201 AC/DC	✓	✓		
PROTIG 201L AC/DC	✓	✓		
TIG 220 AC/DC	✓	✓		
TIG 250 AC/DC	✓	✓		
TITANIUM 230 AC/DC	✓	✓		✓
TITANIUM 400 AC/DC	✓	✓		✓
EXAFEED			✓	
NEOFEED 4W			✓	✓
NEOPULSE 320 C			✓	✓
NEOPULSE 400 CW			✓	✓ (NUM-1 kit required)